Plan Sequence Number: 54982

Section 1. Registration Information

Source Identification

Facility Name: Freeport-McMoRan Sierrita Inc. Parent Company #1 Name: Freeport-McMoRan Copper and Gold

Parent Company #2 Name:

Submission and Acceptance

Submission Type: Re-submission

5-year update (40 CFR 68.190(b)(1)) Subsequent RMP Submission Reason:

Description:

Receipt Date: 23-Jun-2009 Postmark Date: 19-Jun-2009 Next Due Date: 19-Jun-2014 Completeness Check Date: 23-Jun-2009 Yes

Complete RMP:

De-Registration / Closed Reason:

De-Registration / Closed Reason Other Text:

De-Registered / Closed Date:

De-Registered / Closed Effective Date:

Certification Received: Yes

Facility Identification

EPA Facility Identifier: 1000 0009 8388 Other EPA Systems Facility ID: .AZD982478216

Dun and Bradstreet Numbers (DUNS)

Facility DUNS: 173239385 Parent Company #1 DUNS: 187122973

Parent Company #2 DUNS:

Facility Location Address

6200 West Duval Mine Road Street 1:

Street 2:

City: Green Valley State: **ARIZONA** ZIP: 85614

ZIP4:

County: **PIMA**

Facility Latitude and Longitude

Latitude (decimal): 31.876444 -111.100472 Longitude (decimal): GPS - Unspecified Lat/Long Method: Lat/Long Description: Administrative Building

Horizontal Accuracy Measure:

Horizontal Reference Datum Name: World Geodetic System of 1984

Source Map Scale Number:

Plan Sequence Number: 54982

Owner or Operator

Operator Name: Freeport-McMoRan Sierrita Inc.

Operator Phone: (520) 648-8500

Mailing Address

Operator Street 1: PO Box 527

Operator Street 2:

Operator City: Green Valley
Operator State: ARIZONA
Operator ZIP: 85622
Operator ZIP4: 0527

Operator Foreign State or Province:

Operator Foreign ZIP:
Operator Foreign Country:

Name and title of person or position responsible for Part 68 (RMP) Implementation

RMP Name of Person: Chad Fretz

RMP Title of Person or Position: Manager, Environment Land & Water

RMP E-mail Address:

Emergency Contact

Emergency Contact Name: Paul Boman

Emergency Contact Title: Manager, Health & Safety

Emergency Contact Phone: (520) 648-8515 Emergency Contact 24-Hour Phone: (520) 648-8500

Emergency Contact Ext. or PIN:

Emergency Contact E-mail Address: Paul_Boman@FMI.com

Other Points of Contact

Facility or Parent Company E-mail Address:

Facility Public Contact Phone:

Facility or Parent Company WWW Homepage

Address:

Local Emergency Planning Committee

LEPC: Pima County LEPC

Full Time Equivalent Employees

Number of Full Time Employees (FTE) on Site: 985

FTE Claimed as CBI:

Covered By

OSHA PSM:

EPCRA 302 : Yes CAA Title V: Yes

Air Operating Permit ID: M190699P2-99

OSHA Ranking

OSHA Star or Merit Ranking:

Last Safety Inspection

Last Safety Inspection (By an External Agency)

Date:

Last Safety Inspection Performed By an External

Agency:

19-Feb-2009

MSHA

Predictive Filing

Did this RMP involve predictive filing?:

Preparer Information

Preparer Name: Sherry Burt-Kested Preparer Phone: (520) 648-8866

Preparer Street 1: 6200 West Duval Mine Road

Preparer Street 2:

Preparer City: Green Valley
Preparer State: ARIZONA
Preparer ZIP: 85614
Preparer ZIP4:

Preparer Foreign State: Preparer Foreign Country: Preparer Foreign ZIP:

Confidential Business Information (CBI)

CBI Claimed:

Substantiation Provided: Unsanitized RMP Provided:

Reportable Accidents

Reportable Accidents: See Section 6. Accident History below to determine

if there were any accidents reported for this RMP.

Process Chemicals

Process ID: 80207

Description: CI for FeCl3 Regeneration

Process Chemical ID: 106986

Program Level: Program Level 2 process

Chemical Name: Chlorine
CAS Number: 7782-50-5
Quantity (lbs): 360000

CBI Claimed:

Flammable/Toxic: Toxic

EPA Facility Identifier: 1000 0009 8388 Plan Sequence Number: 54982

Process NAICS

 Process ID:
 80207

 Process NAICS ID:
 82171

Program Level: Program Level 2 process

NAICS Code: 212234

NAICS Description: Copper Ore and Nickel Ore Mining

Plan Sequence Number: 54982

Section 2. Toxics: Worst Case

Toxic Worst ID: 52243

Percent Weight:

Physical State: Gas liquified by pressure

Model Used: DEGADIS

Release Duration (mins):10Wind Speed (m/sec):1.5Atmospheric Stability Class:FTopography:Rural

Passive Mitigation Considered

Dikes: Enclosures: Berms: Drains: Sumps:

Other Type:

Plan Sequence Number: 54982

Section 3. Toxics: Alternative Release

Toxic Alter ID: 61621

Percent Weight:

Physical State: Gas liquified by pressure

Model Used: DEGADIS

Wind Speed (m/sec): 3.0
Atmospheric Stability Class: D
Topography: Rural

Passive Mitigation Considered

Dikes: Enclosures: Berms: Drains: Sumps: Other Type:

Active Mitigation Considered

Sprinkler System:
Deluge System:
Water Curtain:
Neutralization:

Excess Flow Valve: Yes

Flares: Scrubbers:

Emergency Shutdown: Yes

Other Type:

Plan Sequence Number: 54982

Section 4. Flammables: Worst Case

No records found.

Plan Sequence Number: 54982

Section 5. Flammables: Alternative Release

No records found.

Plan Sequence Number: 54982

Section 6. Accident History

No records found.

Plan Sequence Number: 54982

Section 7. Program Level 3

Plan Sequence Number: 54982

Section 8. Program Level 2

Description:

Chlorine for FeCl3 Regeneration

Program Level 2 Prevention Program Chemicals

Prevention Program Chemical ID: 30331
Chemical Name: Chlorine
Flammable/Toxic: Toxic
CAS Number: 7782-50-5

Prevention Program Level 2 ID: 28998
NAICS Code: 212234

Safety Information

Safety Review Date (The date of the most recent review or revision of the safety infomation):

25-Jun-2008

Safety Compliance Regulations or Design Codes/Standards

NFPA 58 (or state law based on NFPA 58): Yes

OSHA (29 CFR 1910.111):

ASTM Standards: Yes ANSI Standards: Yes

ASME Standards:

None:

Other Regulation, Design Code, or Standard:

Comments:

DOT Standards

Hazard Review

Hazard Review Date (The date of completion of most recent review or update):

•

Change Completion Date (The expected or actual date of completion of all changes resulting from the

hazard review):

30-Sep-2009

14-Feb-2008

Major Hazards Identified

Toxic Release:

Yes

Fire:

Explosion:

Runaway Reaction: Polymerization: Overpressurization:

Corrosion: Overfilling:

Contamination:

Equipment Failure:

Yes

Loss of Cooling, Heating, Electricity, Instrument Air:

Earthquake:

Plan Sequence Number: 54982

Floods (Flood Plain):

Tornado: Hurricanes:

Other Major Hazard Identified:

Process Controls in Use

Vents:

Relief Valves:

Check Valves: Yes Scrubbers: Yes

Flares:

Manual Shutoffs:YesAutomatic Shutoffs:YesInterlocks:YesAlarms and Procedures:Yes

Keyed Bypass:

Emergency Air Supply: Yes

Emergency Power: Backup Pump:

Grounding Equipment: Inhibitor Addition: Rupture Disks:

Excess Flow Device: Yes

Quench System: Purge System:

None:

Other Process Control in Use:

Mitigation Systems in Use

Sprinkler System:

Dikes:
Fire Walls:
Blast Walls:
Deluge System:
Water Curtain:
Enclosure:

Neutralization: Yes

None:

Other Mitigation System in Use:

Monitoring/Detection Systems in Use

Process Area Detectors:

Perimeter Monitors: Yes

None:

Other Monitoring/Detection System in Use: Video Monitoring System

Changes Since Last PHA or PHA Update

Reduction in Chemical Inventory:

Increase in Chemical Inventory:

Change Process Parameters:

Installation of Process Controls:

Plan Sequence Number: 54982

Installation of Process Detection Systems: Installation of Perimeter Monitoring Systems:

Installation of Mitigation Systems:

None Recommended:

None:

Other Changes Since Last PHA or PHA Update:

Installation of automatic gates to prevent entry

during evacuation

Review of Operating Procedures

Operating Procedures Revision Date (The date of the most recent review or revision of operating procedures): 06-Feb-2008

Training

Training Review Date (The date of the most recent review or revision of training programs):

06-Feb-2008

The Type of Training Provided

Classroom: Yes
On the Job: Yes
Other Training: simulator

The Type of Competency Testing Used

Written Tests:
Oral Tests:
Demonstration

Demonstration: Yes
Observation: Yes

Other Type of Competency Testing Used:

Maintenance

Maintenance Review Date (The date of the most recent review or revision of maintenance procedures):

Equipment Inspection Date (The date of the most recent equipment inspection or test):

Equipment Most Recently Inspected or Tested:

03-Apr-2009

17-Jun-2009

Chlorinator Absorption Tank inspected every 7 days, Chlorinator Tanks inspected every 30 days and pressure tested annually, pumps and unloading stations inspected every 42 days

Compliance Audits

Compliance Audit Date (The date of the most recent 01-Dec-2008 compliance audit):

Audit Completion Date (The expected or actual date of completion of all changes resulting from the compliance audit):

Incident Investigation

Incident Investigation Date (The date of the most recent incident investigation (if any)):

12-May-2005

EPA Facility Identifier: 1000 0009 8388 Plan Sequence Number: 54982

Incident Investigation Changes Date (Expected or actual date of completion of all changes resulting from the investigation):

Most Recent Change Date: (The date of the most recent change that triggered a review or revision of safety information):

09-May-2005

01-Aug-2005

Confidential Business Information

CBI Claimed:

Section 9. Emergency Response

Written Emergency Response (ER) Plan

Community Plan (Is facility included in written community emergency response plan?):

Facility Plan (Does facility have its own written emergency response plan?):

Yes

Response Actions (Does ER plan include specific actions to be taken in response to accidental releases of regulated substance(s)?):

Yes

Public Information (Does ER plan include procedures for informing the public and local agencies responding to accidental release?):

Yes

Healthcare (Does facility's ER plan include information on emergency health care?):

Yes

Emergency Response Review

Review Date (Date of most recent review or update 18-Jun-2009 of facility's ER plan):

Emergency Response Training

Training Date (Date of most recent review or update 18-Jun-2009 of facility's employees):

Local Agency

Agency Name (Name of local agency with which the Green Valley Fire Department facility ER plan or response activities are coordinated):

Agency Phone Number (Phone number of local agency with which the facility ER plan or response activities are coordinated):

(520) 625-9400

Subject to

OSHA Regulations at 29 CFR 1910.38:

OSHA Regulations at 29 CFR 1910.120: Yes
Clean Water Regulations at 40 CFR 112: Yes
RCRA Regulations at CFR 264, 265, and 279.52: Yes
OPA 90 Regulations at 40 CFR 112, 33 CFR 154,

49 CFR 194, or 30 CFR 254:

State EPCRA Rules or Laws: Yes

Other (Specify): MSHA 30 CFR Parts 1 to 199

EPA Facility Identifier: 1000 0009 8388 Plan Sequence Number: 54982

Executive Summary

THE ACCIDENTIAL RELEASE PREVENTION AND EMERGENCY RESPONSE POLICIES AT YOUR FACILITY Each employee of Freeport-McMoRan Sierrita Inc. (Sierrita) is provided with a General Safety and Environmental Handbook which includes the corporate and site-specific safety and health policies.

Sierrita has an excellent record of safety and lost-time accidents. In 1993, 1997, 1999, and 2001, Sierrita received the most prestigious award in the mining industry, the Sentinels of Safety Award. The Sentinels of Safety Award is cosponsored by the American Mining congress and the U.S. Department of Labor is Mine Safety and Health Administration (MSHA) for recognition of achieving one of the best records for number of employee work-hours without a lost-time injury or fatality.

YOUR FACILITY AND THE REGULATED SUBSTANCES HANDLED

Sierrita operates a copper and molybdenum mining and concentrating facility located approximately seven miles west of Green Valley, Arizona. Ore containing low-grade porphyry copper and molybdenum deposits is excavated, crushed, conveyed, milled and concentrated to produce copper and molybdenum concentrates. Copper concentrates are shipped to a smelter for further processing. The molybdenum sulfide concentrate contains a small percentage of copper, which cannot be effectively removed in the flotation process. The copper content in the molybdenum concentrates is lowered using a ferric chloride leach process. A hot ferric chloride solution is agitated in a series of mixing tanks with the molybdenum concentrate. The slurry exiting the tank is a high-grade molybdenum sulfide concentrate. The molybdenum sulfide concentrate is then roasted to yield molybdenum trioxide which is packaged for distribution. The copper leached from the process is recovered as cement copper and sent to a smelter for further processing with the copper concentrates.

The ferric chloride leach liquor is recycled and regenerated using chlorine and iron scrap. Two 90-ton railroad tank cars of chlorine are stored next to the two 7,000 gallon chlorination tanks. One 90-ton railroad tank car of chlorine is connected to a manifold that distributes chlorine to the two 7,000 gallon chlorination tanks while the other is on standby. Typically, three additional back-up chlorine railcars are stored near the chlorinator area. The maximum number of railcars anticipated on-site at any one time would be seven. Each chlorine railcar provides approximately a seven-day supply of chlorine for the chlorination process.

THE GENERAL ACCIDENTAL RELEASE PREVENTION PROGRAM AND CHEMICAL-SPECIFIC PREVENTION STEPS Sierrita is regulated by the Mine Safety and Health Administration (MSHA). MSHA performs comprehensive inspections of the facility for compliance with the Federal Metal and Nonmetallic Mine Safety and Health Standards (30 CFR Parts 1-199). The role of MSHA is to enforce compliance as a means to eliminate fatal accidents, to reduce the frequency and severity of nonfatal accidents, to minimize health hazards, and to promote improved safety and health conditions in the Nation's mines. All Sierrita employees and contractors are required to receive MSHA new miner and annual refresher training including site-specific emergency evacuation procedures.

Several mitigation devices are located in the chlorination area to prevent a chlorine release from occurring. Six chlorine sensors are located around the perimeter of the chlorinator area for identifying the presence of chlorine. The sensors are capable of detecting chlorine in concentrations equal to or greater than 1 ppm. If a release is sensed, the latching relays are de-energized and the two valves from the railcar and the automatic addition valve close. The valves are set up to fail in a closed position in the event of a power or air supply loss. In addition, all chlorine railcars are equipped with check valves, which cut off the chlorine supply if the flow rate were to increase rapidly. Sierrita maintains a chlorine remote video monitoring system in the control room. The system allows a control room operator to monitor the loading and unloading of chlorine railcars. If an incident involving chlorine were to occur during the unloading process, the control room operator could quickly cease the chlorine supply from the control room.

The chlorination system is also equipped with an absorption system to prevent over-chlorination of the process, which may result in a chlorine release. The absorption system consists of a 265-gallon tank containing 25% caustic soda solution. Chlorine in excess of the process required amount is vented to the chlorination tank, where it is neutralized. The tank is emptied and recharged daily and a detailed inspection is conducted every 7 days by trained Molybdenum Operations personnel.

Sierrita has prepared written operating procedures, also known as ¿Tasks¿, in accordance with the Molybdenum Processing certified International Standards Organization (ISO) 9000 system. The procedures are written to provide clear instruction or steps for safely conducting activities associated with each covered process

Monthly inspections are performed for each of the storage tanks in the chlorination area and an annual pressure test is conducted

EPA Facility Identifier: 1000 0009 8388 Plan Sequence Number: 54982

with water on each chlorination tank. The inspections are used to monitor any signs of tank deterioration, leaking and corrosion of tanks, valves and all associated piping. In addition, an annual hydrostatic leak test is performed on all chlorine lines and unloading hoses are replaced annually.

Sierrita conducts a hazard review at least once every five years in order to identify hazards associated with: the process and chlorine; opportunities for equipment malfunctions or human errors that could cause an accidental release; the safeguards used or needed to control the hazards or prevent equipment malfunction or human error; and any steps used or needed to detect or monitor releases. The most recent hazard review was conducted in February, 2008. In addition, Sierrita periodically invites its chlorine supplier, Olin Chlor Alkali Products to conduct a Responsible Management Review. The most recent Responsible Management Review was conducted in July, 2008. Every three years, Sierrita performs a compliance audit to assess compliance with the Risk Management Program. The compliance audit team consists of personnel knowledgeable in the chlorinator process and Program requirements. The most recent compliance audit was completed in December, 2008. Only minor recommendations resulted from the most recent reviews and audit and all recommended actions will be completed by September, 2009.

THE FIVE YEAR ACCIDENT HISTORY

Sierrita has had no chlorine releases in the past five years requiring medical treatment other than minor first aid. As a safety precaution, Sierrita requires first aid for any and all types of chlorine releases, regardless of the extent of the release. There have been no reportable releases and no environmental impacts from chlorine releases.

THE EMERGENCY RESPONSE PROGRAM

Sierrita developed a detailed Chlorine Emergency Response (ER) Plan which addresses general and chemical specific emergency response procedures. Sierrita offers the ER Plan to the Pima County Sherriff¿s Department, Pima county Local Emergency Planing Committee (LEPC), Green Valley Fire Department, Arizona Emergency Response Commission (AZERC), and St. Mary¿s Hospital for local emergency response coordination.

In the event of a chlorine release, an audible alarm will sound in various facilities at the site. Evacuation routes have been developed and are posted throughout the entire Sierrita Plant site. Sierrita has several trained first responders and a Hazmat team to respond to incidents.

PLANNED CHANGES TO IMPROVE SAFETY

Sierrita conducted a Hazard Review in February 2008 and invited its chlorine supplier Olin Chlor Alkali Products to conduct a Responsible Management Review in July, 2008. Only minor recommendations were made during these reviews and all have been completed except the review and update (if needed) of detailed process and instrumentation drawings which will be completed by September, 2009. No other changes are planned to improve safety.